

PLAT OF BUCKSKIN HEIGHTS FIRST SUBDIVISION  
SITUATE IN SECTION 33 AND SECTION 34, TOWNSHIP 7 NORTH, RANGE 70 WEST  
OF THE SIXTH P.M., LARIMER COUNTY, COLORADO

©1970-2023 Buckskin Heights Road Association

## ENGINEER'S CERTIFICATE:

James H. Stewart, a Professional Engineer and Land Surveyor under the Laws  
of the State of Colorado, being duly sworn on his oath, deposes and says  
that the survey and plat of Buckskin Heights First Subdivision were made  
under his supervision, that said plat is an accurate delineation of said survey,  
that he has read the statements thereon, and that the same are true of  
his own knowledge.

James H. Stewart  
James H. Stewart  
Professional Engineer & Land Surveyor

Subscribed and sworn to before me this 8<sup>th</sup> day of October A.D. 1970

Judith L Johnson  
Notary Public

My notarial commission expires November 8, 1971

STATEMENT OF OWNERSHIP, SUBDIVISION AND DEDICATION:


KNOW ALL MEN BY THESE PRESENTS: That, John O. Anderson, being the owner of the following described land, to-wit: A tract of land situate in Sections 33 and 34, Township 7 North, Range 70 West of the Sixth P.M., Larimer County, Colorado, which, considering the South line of said Section 33 as bearing  $588^{\circ}54'W$  and with all bearings contained herein relative thereto, is contained within the boundary lines which begin at the Southeast corner of said Section 33 and run thence  $588^{\circ}54'W$  5175.72 feet to the Southwest corner of said Section 33; thence  $N00^{\circ}46'W$  2713.26 feet to the West  $\frac{1}{4}$  corner of said Section 33; thence  $N36^{\circ}52'20"E$  2235.64 feet; thence  $S45^{\circ}45'E$  536.38 feet; thence  $S29^{\circ}32'E$  248.32 feet; thence  $S16^{\circ}15'E$  180.22 feet; thence along the arc of a 143.12 foot radius curve to the left a distance of 68.65 feet, the long chord of which bears  $S29^{\circ}59'30"E$  67.99 feet; thence  $S43^{\circ}44'E$  95.73 feet; thence  $S63^{\circ}05'E$  177.31 feet; thence along the arc of a 88.97 foot radius curve to the left a distance of 75.18 feet, the long chord of which bears  $S87^{\circ}17'30"E$  72.97 feet; thence  $N68^{\circ}30'E$  42.19 feet; thence along the arc of a 96.77 foot radius curve to the left a distance of 75.86 feet, the long chord of which bears  $N46^{\circ}02'30"E$  73.94 feet; thence  $N23^{\circ}35'E$  58.35 feet; thence along the arc of a 82.76 foot radius curve to the right a distance of 103.83 feet, the long chord of which bears  $N59^{\circ}31'30"E$  97.15 feet; thence  $S84^{\circ}32'E$  62.12 ft.; thence  $N00^{\circ}37'W$  373.73 feet; thence  $N89^{\circ}52'E$  -304.97 feet; thence along the arc of a 135.63 foot radius curve to the left a distance of 126.01 feet, the long chord of which bears  $S43^{\circ}47'E$  121.53 feet; thence  $S70^{\circ}24'E$  198.70 feet; thence along the arc of a 104.07 foot radius curve to the right a distance of 76.38 feet, the long chord of which bears  $S49^{\circ}22'30"E$  74.67 feet; thence  $S28^{\circ}21'E$  124.39 feet; thence along the arc of a 190.89 foot radius curve to the right a distance of 325.17 feet, the long chord of which bears  $N83^{\circ}23'E$  287.26 feet; thence  $S47^{\circ}49'E$  277.24 feet; thence  $S58^{\circ}42'E$  283.61 feet; thence along the arc of a 60.00 foot radius curve to the left a distance of 101.70 feet, the long chord of which bears  $N72^{\circ}44'30"E$  89.96 feet; thence along the arc of a 53.54 foot radius curve to the left a distance of 45.74 feet, the long chord of which bears  $N00^{\circ}17'30"W$  44.36 feet; thence  $N24^{\circ}46'W$  27.40 feet; thence along the arc of a 187.16 foot radius curve to the right a distance of 116.13 feet, the long chord of which bears  $N06^{\circ}59'30"W$  114.27 feet; thence  $N10^{\circ}47'E$  58.15 feet; thence along the arc of a 106.12 foot radius curve to the right a distance of 130.58 feet, the long chord of which bears  $N46^{\circ}02'E$  122.49 feet; thence  $N23^{\circ}34'20"W$  440.73 feet; thence  $N89^{\circ}33'E$  1285.00 feet; thence  $S00^{\circ}27'E$  200.00 feet; thence  $S83^{\circ}13'E$  28.81 feet; thence along the arc of a 112.26 foot radius curve to the left a distance of 94.08 feet, the long chord of which bears  $N72^{\circ}46'30"E$  91.35 feet; thence  $N48^{\circ}46'E$  97.52 feet; thence  $N58^{\circ}54'15"E$  1293.37 feet; thence  $S00^{\circ}19'30"E$  4648.84 feet to a point on the South line of said Section 34; thence  $S88^{\circ}54'W$  1293.93 feet to the point of beginning, has caused the same to be surveyed and subdivided into lots and streets as shown on this plat to be known as BUCKSKIN HEIGHTS FIRST SUBDIVISION. All roads and streets shown on this plat are private for the private use and benefit of the owners of the lots and their invitees, however, all roads shown on this plat are to be reserved as perpetual easements for the installation and maintenance of utilities and drainage facilities. Also, all easements shown on this plat are hereby reserved as perpetual easements for the installation and maintenance of utilities, and irrigation and drainage facilities.

John O. Anderson  
John O. Anderson

State of Colorado}  
County of Larimer} ss:

The foregoing instrument was acknowledged before me this 8<sup>th</sup> day of October A.D. 1970, by  
John O. Anderson as owner of BUCKSKIN HEIGHTS FIRST SUBDIVISION.

My notarial commission expires January 8, 1971



The description of the access road to Buckskin Heights First Subdivision from the County Road in Section 15, Township 6 North, Range 70 West of the Sixth P.M., Larimer County, Colorado, is recorded in Book 1444 at Page 325 of the Larimer County Clerk & Recorder's Office.

PLAT OF BUCKSKIN HEIGHTS FIRST SUBDIVISION

©1970-2023 Buckskin Heights Road Association


APPROVAL: By the Larimer County Planning Commission this 14th day of October A.D. 1970. This approval does not constitute acceptance by the Board of County Commissioners of the County of Larimer of a dedication to public use of streets or other property contained in this plat, which acceptance can be given only by action of the Board of County Commissioners of the County of Larimer. Until such acceptance shall be made, the County of Larimer assumes no responsibility for the construction, repair or maintenance of the streets laid out or dedicated hereon.

By: Thomas C. Bean  
Chairman

Attest: Edwin N. Hans  
Secretary

APPROVAL: By the Larimer County Health Authority this 13th day of October A.D. 1970.  
construction on this subdivision or any lot therein, including the development of domestic water and  
provision of sewage disposal, shall be done in a manner which will meet all the requirements of the  
Colorado Department of Health and the Larimer County Public Health Department and the officials  
authorized to enforce such requirements.

Arthur E. Gerhard  
Larimer County Health Auth



988545

No.

Buckskin Heights 1st

Sub.

Grantor

TO

Miss

Grantee

4652 OCT 21

'70 OCT 21 PM

STATE OF COLORADO  
LARIMER COUNTY  
CERTIFIED AND FILED  
CLERK AND RECORDER

County of Larimer  
State of Colorado

I hereby certify that this instrument was filed for record in my office at 12:00 o'clock

M.

OCT 21 1970

and

is duly recorded in book 1444

at page : 679 P 8 F 3 # 26

Recorder

James P. Thompson

Deputy

By

Gray W. Greison

# PLAT OF BUCKSKIN HEIGHTS SECOND SUBDIVISION


SITUATE IN THE SOUTH 1/2 OF SECTION 28, AND THE SOUTHEAST 1/4 OF SECTION 29, AND THE NORTHEAST 1/4 OF SECTION 32, AND THE NORTH 1/2 OF SECTION 33, AND THE NORTHWEST 1/4 OF SECTION 34, TOWNSHIP 7 NORTH, RANGE 70 WEST OF THE SIXTH P.M., LARIMER COUNTY, COLORADO

©1970-2023 Buckskin Heights Road Association

## STATEMENT OF OWNERSHIP, SUBDIVISION, AND DEDICATION:

KNOW ALL MEN BY THESE PRESENTS: That, John O. Anderson, being the owner of the following described land, to-wit: A tract of land situate in Sections 28, 29, 32, 33, and 34, Township 7 North, Range 70 West of the Sixth P.M., Larimer County, Colorado, which, considering the South line of said Section 33 as bearing 388°54'W and with all bearings contained herein relative thereto, is contained within the boundary lines which begin at the West 1/4 corner of said Section 33 and run thence N36°52'20"E 2235.64 feet; thence S45°45'E 536.38 feet; thence S29°32'E 248.32 feet; thence along the arc of a 143.12 foot radius curve to the left a distance of 68.66 feet, the long chord of which bears S29°59'30"E 67.99 feet; thence S43°44'E 95.73 feet; thence S63°05'E 177.31 feet; thence along the arc of a 88.97 foot radius curve to the left a distance of 75.18 feet, the long chord of which bears S87°17'30"E 72.97 feet; thence along the arc of a 96.77 foot radius curve to the left a distance of 75.86 feet, the long chord of which bears N46°02'30"E 73.94 feet; thence N23°35'E 58.35 feet; thence along the arc of a 82.76 foot radius curve to the right a distance of 103.83 feet, the long chord of which bears N59°31'30"E 97.15 feet; thence S84°32'E 62.12 feet; thence N00°37'W 373.73 feet; thence along the arc of a 135.63 foot radius curve to the left a distance of 126.01 feet, the long chord of which bears S43°47'E 121.53 feet; thence S70°24'E 198.70 feet; thence along the arc of a 104.07 foot radius curve to the right a distance of 76.38 feet, the long chord of which bears S49°22'30"E 74.67 feet; thence S28°21'E 124.39 feet; thence along the arc of a 190.89 foot radius curve to the right a distance of 325.17 feet, the long chord of which bears N83°23'E 287.26 feet; thence S47°49'E 277.24 feet; thence along the arc of a 60.00 foot radius curve to the left a distance of 101.70 feet, the long chord of which bears N72°44'30"E 89.96 feet; thence along the arc of a 53.54 foot radius curve to the left a distance of 45.74 feet, the long chord of which bears N00°17'30"E 44.36 feet; thence N24°46'W 27.40 feet; thence along the arc of a 187.16 foot radius curve to the right a distance of 116.13 feet, the long chord of which bears N06°59'30"W 114.27 feet; thence along the arc of a 106.12 foot radius curve to the right a distance of 130.58 feet, the long chord of which bears N46°08'E 122.49 feet; thence N23°34'20"W 440.73 feet; thence N89°33'E 1285.00 feet to a point on the East line of the Northeast 1/4 of said Section 33; thence, along said East line, 500' E, 200.00 feet; thence S83°13'E 28.81 feet; thence along the arc of a 112.26 foot radius curve to the left a distance of 94.08 feet, the long chord of which bears N72°46'30"E 91.35 feet; thence N58°54'15"E 1334.35 feet; thence S89°23'W 1304.04 feet to a point on the East line of the Southeast 1/4 of said Section 28; thence N89°28'W 5267.11 feet to the Northwest corner of the Southwest 1/4 of the Southwest 1/4 of said Section 28; thence S87°08'W 1301.19 feet; thence N01°30'W 1355.61 feet; thence S87°03'W 507.58 feet; thence S37°44'30"E 150.52 feet; thence along the arc of a 228.84 foot radius curve to the right a distance of 135.86 feet, the long chord of which bears S33°53'30"E 133.88 feet; thence S16°53'E 80.22 feet; thence along the arc of a 57.14 foot radius curve to the left a distance of 102.57 feet; thence S46°57'W 102.57 feet; thence along the arc of a 60.00 foot radius curve to the left a distance of 134.88 feet, the long chord of which bears S54°02'30"W 100.35 feet; thence S02°42'E 315.18 feet; thence along the arc of a 185.42 foot radius curve to the left a distance of 165.45 feet, the long chord of which bears S67°17'E 158.95 feet; thence along the arc of a 55°36'30"E 86.55 feet; thence S70°42'E 156.64 feet; thence N84°44'E 112.87 feet; thence along the arc of a 169.38 foot radius curve to the right a distance of 97.68 feet, the long chord of which bears N89°12'E 478.98 feet; thence S39°8'E 75.97 feet to a point on the West line of the Southwest 1/4 of said Section 28; thence S01°55'E 984.75 feet; thence S00°46'E 711.26 feet; thence S61°57'10"W 1480.69 feet; thence S00°29'30"E 1344.88 feet; thence N88°18'E 1322.64 feet to the point of beginning, has caused the same to be surveyed and subdivided into lots and streets as shown on this plat to be known as BUCKSKIN HEIGHTS SECOND SUBDIVISION. All roads and streets shown on this plat are private for the private use and benefit of the owners of the lots and their invitees, however, all roads shown on this plat are to be reserved as perpetual easements for the installation and maintenance of utilities and drainage facilities. Also, all easements shown on this plat are hereby reserved as perpetual easements for the installation and maintenance of utilities, irrigation, and drainage facilities.


WITNESS my hand and seal this 30th day of December, A.D. 1970.

  
John O. Anderson

State of Colorado,  
County of Larimer,


The foregoing instrument was acknowledged before me this 30th day of December, A.D. 1970, by John O. Anderson as owner of BUCKSKIN HEIGHTS SECOND SUBDIVISION.

  
Notary Public  
My notarial commission expires November 8, 1971





## ENGINEER'S CERTIFICATE:

James H. Stewart, a Professional Engineer and Land Surveyor under the Laws of the State of Colorado, being duly sworn on his oath, deposes and says that the survey and plat of Buckskin Heights Second Subdivision were made under his supervision, that said plat is an accurate delineation of said survey, that he has read the statements thereon, and that the same are true of his own knowledge.

  
James H. Stewart  
Professional Engineer & Land Surveyor


Subscribed and sworn to before me this 11<sup>th</sup> day of February A.D. 1971.


  
J. R. Robinson  
Notary Public  
My notarial commission expires November 8, 1971



## APPROVAL:


By the Larimer County Planning Commission this 10 day of February A.D. 1971. This approval does not constitute acceptance by the Board of County Commissioners of the County of Larimer of any dedication to public use of streets or other property contained in this plat, which acceptance can be given only by action of the Board of County Commissioners of the County of Larimer. Until such acceptance shall be made, the County of Larimer assumes no responsibility for the construction, repair or maintenance of the streets, laid out or dedicated hereon.


By:   
Edwin M. Weston

Attest:   
W. B. Hanna  
Secretary

## APPROVAL:

By the Larimer County Health Authority this 2nd day of February A.D. 1971. All construction on this subdivision or any lot therein, including the development of domestic water and the provision of sewage disposal, shall be done in a manner which will meet all the requirements of the Colorado Department of Health and the Larimer County Public Health Department and the officers authorized to enforce such requirements.

  
Arthur E. Grahams  
Larimer County Health Authority



## PUBLIC HEALTH COVENANT:

This subdivision is not provided with public sewer facilities. Permits must be obtained before the installation of any sanitary disposal system. Approval of plat does not guarantee that the size or soil conditions of any lot shown herein are such that a sewage disposal permit may be issued. It is also hereby agreed by the subdivider, his heirs, successors, and assigns, that in the event that the proper authorities of the Larimer County Health Department shall determine that the surface or subsurface water in the area is becoming contaminated by the use of septic tanks, the owners of the properties in the subdivision shall install, at their own expense, a commercial or private sewage disposal system. This is a covenant running with the land.


SHEET NO. 1 OF 2.

PLAT OF BUCKSKIN HEIGHTS SECOND SUBDIVISION

SITUATE IN THE SOUTH 1/2 OF SECTION 28, AND THE SOUTHEAST 1/4 OF SECTION  
32, AND THE NORTH 1/2 OF SECTION 33, AND THE NORTHWEST 1/4 OF SECTION 34, TOWNSHIP 7 NORTH, RANGE 70  
WEST OF THE SIXTH P.M., LARIMER COUNTY, COLORADO

©1970-2023 Buckskin Heights Road Association

N.W. Corner of S.W. 1/4  
of S.W. 1/4 of  
Section 28-7-70



No. 595345

Plat

Buckskin Heights  
Second Subdivision

Misc.

TO	71	Grantor
SELLER	WHR	STATE
John	10 AM	CITY OF COLORADO
John	10 AM	COFFEE COUNTY
County of Larimer State of Colorado	ss.	RECEIVED FILED APR 11 1971

I hereby certify that this instrument was filed for

record in my office at 10:10 o'clock

A M., MAR 10 1971 1971, and

is duly recorded in book 1455

at page 27 P8 F5 #2

James P. Thompson

Recorder

Constance DeTheye

Deputy

**VAULT**

70 RE. 10 H 10.00 ..